

BUILDING SAFETY CERTIFICATE**No. 816****Dated: 23-05-2025**

It is certified that the existing building **SARVHITKARI VIDYA MANDIR, BHIKHI** (Name of the building or premises) at Moola Singh Wala Road, Bhikhi , Distt. Mansa (Punjab) Pin code 151504 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	2	-	-	-	-


The building is owned/occupied by **SARVHITKARI VIDYA MANDIR, BHIKHI** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD & BR Office Mansa** (Name of Department/ Govt.) on **12-05-2025** (date of inspection) in the presence of Sh. Amrit Lal (Manager) & Dr. Gagandeep Prashar (Principal) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **23-05-2025** for a period of **31-03-2026** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing Capacity, Foundation details, structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/ to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. Immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building **66502 Sq.Ft.** which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year **2025-26**

As per visually inspection as reported by the concerned Assistant/ Junior Engineer the above building may be used for normal use for One year up to **31-03-2026** subject to the above conditions.

Issued on **23-05-2025** at **Mansa** by

Assistant Junior Engineer


Sub Divisional Engineer,
Prov. Sub Divn. No.1 PWD (B&R)
Mansa

Signature with Seal :

Name : Harpreet Singh

Designation: Sub Divisional Engineer,

Name & Address of Department/ Office : PWD (B & R)

Mansa